



INSPECTION REPORT

JAN 10 2008

861 cust_id
308248 insp_id
5413 site_id

RESEARCH TRIANGLE INSTITUTE

Customer ID: 861

Certificate: 55-R-0002

P.O. BOX 12194 3040 CORNWALLIS RD.
RESEARCH TRIANGLE PA, NC 27709

Site: 001

RESEARCH TRIANGLE INSTITUTE

Inspection

Type: ROUTINE INSPECTION

Date: DEC-19-2007

3.51 (d)

FACILITIES, INDOOR.

Interior surfaces. The interior building surfaces of indoor housing facilities shall be constructed and maintained so that they are substantially impervious to moisture and may be readily sanitized.

***In Room 404, there is a crack on the wall near the ceiling where the seal has popped open between the cinder block wall and the filled in area around a pipe. Need to repair the seal so that the wall is impervious to moisture. Correct by January 30, 2008.

3.56 (c)

SANITATION.

Housekeeping. Premises (buildings and grounds) shall be kept clean and in good repair in order to protect the animals from injury and to facilitate the prescribed husbandry practices set forth in this subpart.

***In rabbit rooms 408 and 410, there is an excessive accumulation of urine scale on the walls and floors. In room 410, some of the wall paint is beginning to peel off due to the male rabbit urine spraying. Need to thoroughly sanitize these rooms to remove urine scale. Also need to plan room changes for long-term rabbit studies so that rooms can be sanitized at regular intervals. Correct by January 30, 2008.

Prepared By:


F BINKLEY, D V M, USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER , Inspector ID: 1020

Date:

DEC-19-2007

Received By:

Date:

DEC-19-2007

Title: